



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

July 16, 2007

Supervisor 10374

Mine Name: Brown's Canyon Quarry
Operator Name: Mountain Valley Stone, Inc

Permit number: M/043/019
Inspection Date: July 16, 2007
Time: 1:30 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Robert Hicken, Tony Branca
Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:

This site was active. The well has been competed and a water tank has been placed so that the operator could fill a water truck for dust suppression. Road and active pad areas are sprinkled regularly to control fugitive dust. D&C Transport has set up a crusher to crush waste rock. Dust suppression was operational with no visible dust coming from the crusher.

Operations were all within the permitted area. All areas currently permitted and bonded, however, have not been disturbed. Topsoil is being stripped and stockpiled as operations and pad areas advance.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The only area of concern was along the eastern boundary the permit area (adjoins the Peoa Blonde Quarry -M/043/012) Thistle were advancing onto the site. Mr. Hicken indicated he would have someone take care of this concern.

Inspector's Signature

LK:pb

O:\M043-Summit\M0430019-BrownsCym-MVS\Inspections\Insp-07162007.doc